


Concrete Scan Report

ID: ONT0023MAD20161017
17 Oct 2016

Client	Site
Proper Plumbing Pty Ltd 45 Otter Avenue Brookvale NSW 2100 Contact: Paul Franklin (0438278901)	Westfield Bondi Junction Adelaide Street Bondi Junction NSW 2202 Contact: Peter Jonhson (0434674562)

Client PO#	44456	Instrument #1	MALA CX GPR / 1.6GHz-EM
Client Reference	Roof top antennae mounting	Instrument #2	RD8000 Wand
Targets	<input checked="" type="checkbox"/> PT <input checked="" type="checkbox"/> POWER <input type="checkbox"/> STEEL <input type="checkbox"/> CONDUIT <input type="checkbox"/> STRUCTUAL SCAN <input type="checkbox"/> VOIDING		
Site Markings	<input checked="" type="checkbox"/> CRAYON <input type="checkbox"/> SPRAY MARKS <input type="checkbox"/> TAPE <input type="checkbox"/> TARGET STICKER <input type="checkbox"/> OTHER		



Information Summary

Findings as marked onsite.
Power cable detected and marked onsite.
Top (blue) and bottom (green) steel marked onsite.
Acces to underside of slab requested. This was refused because it is another tenant.
Site manager offered a walk through of the findings. This was refused due to time constraints.

Operator:	Warren McKensi	Phone:	0438 278 902
-----------	----------------	--------	--------------


Total Cost:	675.00 + GST
-------------	--------------

Signature by:	Peter Jonhson	
<small>Whilst every effort will be made to identify potential hazards, the deployed technology does not necessarily identify all potential hazards. No representation or warranty is made to the effect that all risk is completely eliminated. Our service is to minimise your risk but we do not promise to eliminate risk. Please contact us for full disclaimer.</small>		

Images




Site picture without overlay markings




Top steel at 110mm below the surface

Images



Power cable running on a diagonal at 193mm depth



Bottom steel at 327mm below the surface.